



उत्तर प्रदेश पावर कारपोरेशन लिमिटेड

(उत्तर प्रदेश सरकार का उपक्रम)

U P POWER CORPORATION LTD.

(Govt. of Uttar Pradesh Undertaking)

CIN:U32201UP1999SGC024928

संख्या-3086-कार्य/चौदह-पाकालि/2019-8(53)-के/2019

दिनांक 17 दिसम्बर, 2019

प्रबन्ध निदेशक,
पूर्वान्चल/मध्यांचल/दक्षिणान्चल/
पश्चिमांचल, विद्युत वितरण निगम लि०,
वाराणसी/लखनऊ/आगरा/मेरठ,
केरको, कानपुर।

Sub: Blacklisting for the period of 3 years, on account of failure of sample in Shriram Institute for Industrial Research, New Delhi against Purchase Order no. DH-1596/RC-105/QH-II/1930/XEN/MM-II dated 15.11.2017 and DH-1636/RC-105/QH-II/1930/XEN/MM-II dated 05.02.2018Due to failure of sample in NABL testing thereof.

महोदय,

कृपया उपरोक्त विषयक Chief Engineer/MM Dakshin Haryana Bijli Vitran Nigam, Hisar के Memo. No. Ch-91/DH-1596/RC-105/QH-II/1930/XEN/MM-II दि० 07.10.2019 जो कि M/s Himachal Wire Industries Pvt Ltd., Industrial Avenue, G.T. Road, Damtal, Dist. Kangra -176403 (HP) को Blacklist किये जाने के सम्बन्ध में है, का सन्दर्भ ग्रहण करें।

उपरोक्त पत्र की छायाप्रति प्रेषित करते हुए मुझे आपसे यह अनुरोध करने का निदेश हुआ है कि कृपया उक्त पत्र को संज्ञान में लेते हुए तदनुसार कार्यवाही करने का कष्ट करें।

संलग्नक:-यथोपरि।

भवदीय

(आर०के० श्रीवास्तव)
उप सचिव (कार्य)

संख्या-3086-(1)-कार्य/चौदह-पाकालि/2019 तददिनांक

प्रतिलिपि निम्नलिखित को सूचनार्थ एवं अग्रेतर कार्यवाही हेतु प्रेषित:-

1. प्रबन्ध निदेशक, उ०प्र० पावर ट्रान्समिशन कारपोरेशन लि०/राज्य विद्युत उत्पादन निगम लि०/उ०प्र० जल विद्युत निगम लि०, शक्ति भवन, लखनऊ।
2. Chief Engineer/MM Dakshin Haryana Bijli Vitran Nigam, Hisar को उनके Memo. No. Ch-91/DH-1596/RC-105/QH-II/1930/XEN/MM-II दि० 07.10.2019 के सन्दर्भ में।
3. उप महाप्रबन्धक (लेखा प्रशासन), उ०प्र० पावर कारपोरेशन लि०, शक्ति भवन, लखनऊ।
4. अधिशासी अभियन्ता (वेब), कक्ष संख्या-407, उ०प्र० पावर कारपोरेशन लि०, शक्ति भवन विस्तार, लखनऊ को वेबसाइट-www.uppcl.org पर अपलोड करने हेतु।


संलग्नक:-यथोपरि।

(आर०के० श्रीवास्तव)
उप सचिव (कार्य)

10269

वि. (का. प्र. एवं प्रशा.) राजाजी

पत्र सं. 327 कार्य-14/पत्रकालि 2019
क्रम सं. 1 दिनांक
पत्रावली सं. 8(53)के/19

	DAKSHIN HARYANA BIJLI VITRAN NIGAM (A Govt. of Haryana Undertaking) An ISO:9001:2008 Certified Company Office of the Chief Engineer/MM, Vidyut Sadan, Vidyut Nagar, Hisar - 125005-06 (Haryana) Tel: 01662-223061, Fax No. 01662-223005 (SE:01662-223332) Website: www.dhbvn.com Email: semm@dhbvn.org.in
---	---

Memo no. Ch-91 /DH-1596/RC-105/QH-II/1930/XEN/MM-II Date: - 7.10.2019
To,

Regd. Post M/s Himachal Wire Industries Pvt Ltd., Email:-subhash.mahajan@himachalwire.com,
Industrial Avenue, G.T. Road, Damtal, biz.enquiry@himachalwire.com,
Distt.Kangra-176403 (HP).

Subject: - Blacklisting for a period of 3 years, on account of failure of sample in Shriram Institute for Industrial Research, New Delhi against Purchase Orders no. DH-1596/RC-105/QH-II/1930/XEN/MM-II dated 15.11.2017 and DH-1636/RC-105/QH-II/1930/XEN/MM-II dated 05.02.18 ----- Due to failure of sample in NABL testing thereof.

2656/CM/2019
28/11/2019

Two no. purchase order (P.O. no. DH-1596 & DH-1636) were placed upon your firm for supply of 208 MT, GI wire 8 SWG (4mm) against rate contract no. 105/QH-II/1930/UHBNV/P-IV/MM dated 20.02.2017. After receipt of material in stores, sample selected & sealed by the PRI committee were got tested from NABL approved lab as per provision of RC/PO. However, the samples selected from five no. lots of G.I wire supplied by firm against ibid POs did not confirm to the IS: 280: 2006. Thus, the qty. of 130 MT related to these five lots is lying rejected in stores but the firm did not replace the rejected material. However, PO wise status is elaborated as under: -

A- Purchase Order No. DH-1596/RC-105/QH-II/1930/XEN/MM-II dated 15.11.17
Purchase Order No. DH-1596/RC-105/QH-II/1930/XEN/MM-II dated 15.11.17 was placed upon M/s Himachal Wire Industries Pvt. Ltd., Distt. Kangra for supply of 104 MT, GI wire 8 SWG (4mm). Accordingly, after getting pre dispatch inspections of the material by DHBVN officers, dispatch instructions (4 Lots) were issued by MM office for supply of material to designated Nigam's Stores. The status of material supplied by the firm and sample testing thereof from NABL lab is elaborated as under:-

न (क. 8.)

सि
धु
28.11.19
(डी० के० शर्मा)
निजी सचिव
अध्यक्ष, उ०प्र० कां०

Sr. No.	Description of Material	D.I no. & Date	Qty. in MT	Sample testing status & issue- ability
1	G.I Wire 8 SWG (4 mm)	Ch-10/DH-1596 dated 25.01.18	26	Lot made issuable without sending sample.
		Ch-18/DH-1596 dated 23.02.18	26	Sample results did not found in order.
		Ch-26/DH-1596 dated 20.03.18	26	Sample test results were found in order.
4		Ch-31/DH-1596 dated 05.04.18	26	Sample results did not found in order.
			104	

अ०फ०I

28/11
निदेशक
उ०प्र० कां०

From the above, it is evident that out of the 104 MT G.I Wire 8 SWG (4 mm) supplied by your firm, the material of 2 lots (52 MT) failed in testing from NABL lab M/s Shri Ram Institute for Industrial Research, New Delhi. As per test report, sample selected and sealed from DI no. Ch-18/DH-1596 dated 23.02.18 did not confirm to the IS: 280: 2006 as Mass of Zinc Coating on G.I. Wire was not found within permissible limit. Similarly, sample selected and sealed from DI no. Ch-31/DH-1596 dated 05.04.18 did not conform to IS: 280: 2006 as values observed for Mass of Zinc Coating on G.I. Wire was not found within permissible limit.

28.11.19
2
20/11/19

Your firm vide MM office memo nos. Ch-35/DH-1596/RC-105 dated 28.04.18 and Ch-50/DH-1596/RC-105 dated 02.07.18 was requested to replace the aforementioned material. Further on request on your firm, re-sampling and re-testing of G.I Wire 8 SWG (4 mm) from the lot of D.I. no. Ch-18/DH-1596/RC-105 dated 23.02.18 was requested. The status of material supplied by the firm and sample testing thereof from NABL lab is elaborated as under:-

34 श्रीराम (क. 8.)
29/11/19

D:\Wire\G.I Wire\QH-1930\DH-1596\Blacklisting Letter.docx

29/11
अपर सचिव (प्रथम)

20/11
30/11/19

1596 dated 23.02.18 was allowed vide MM office memo no. Ch-46/DH-1596 dated 06.06.2018. But, the sample again failed on testing at M/s Shri Ram Institute for Industrial Research, New Delhi as Mass of Zinc Coating on G.I. Wire was not found within permissible limit. Accordingly, your firm was requested to replace the rejected material vide MM office memo no.Ch-57/DH-1596 dated 25.07.2018. But inspite of repeated reminders, your firm did not take keen interest to replace the said material of 2 lots rejected by Nigam.

The detailed case as above was considered by SPC in its meeting held 04.01.2019 and observed that the GI wire 8 SWG (4mm) supplied by your firm have repeatedly failed in quality tests which shows that your firm is not adhering to quality of material as per Nigam's Technical Specifications and has supplied the sub-standard material. Accordingly, after due deliberation, SPC decided to recommend to WTDs as per details noted below:-

1. To reject the material of 52 MT G.I Wire received against DI no. Ch-18 dated 23.02.18 (26 MT) & Ch-31 dated 05.04.18 (26 MT) of MM office P.O. No. DH-1596/RC-105 dated 15.11.17 supplied by M/s Himachal Wire Industries Pvt Ltd., Distt. Kangra on account of failure of sample. The firm shall be asked to lift back the rejected material after recovery of all the penalties/LD charges etc.
2. To recover the cost of sample testing from the firm alongwith expenditure incurred by Nigam for conducting pre-dispatch inspection of the aforementioned (qty. against 2 no. D.Is). In addition to this, a penalty@5% of cost of the rejected lot of material shall also be recovered from the firm by FA & CAO/MM, DHBVN, Hisar.
3. The Purchase Order No. DH-1596RC-105/QH-II/1930/XEN/MM-II dated 15.11.2017 may be terminated and Liquated damages (L.D.) charges @ 5% of cost of the material rejected in NABL testing and lying in stores i.e. 52 MT, GI Wire received against PO No. DH-1596/RC-105/QH-II/1930/XEN/MM-II dated 15.11.17 may be imposed upon the firm.
4. In case of non-deposit of amount of penalties and LD charges etc. as per sr. no. 2 and 3 above, the Nigam may set off the claim from the due payments (including security deposits returnable to the supplier) of firm or firm's B.G. may be encashed to set off the pending liabilities of the Nigam & balance payment, if left-out (after clearance of all liabilities of Nigam) may be refunded to the firm.
5. Action against the firm for blacklisting for a period of next three years on account of supply of sub-standard material, may be initiated by serving notices of 15 and 21 days to the firm.

As per recommendation of SPC, the case was considered by the WTDs of DHBVN in its meeting held on 09.02.19 against agenda item no. 178.15 decided to approve the above proposals mentioned from point no. 1 to 5.

Accordingly, a notice of 15 days was served upon your firm vide MM office memo no Ch-65/DH-1596 dated 25.02.19 to explain the position as to why the firm should not be blacklisted on account of supplying the below standard material to Nigam and thus indulging in breach of contract in completing the supplies against subject cited P.O. But no response was received from your firm. Accordingly, a final notice of 21 days was served upon your firm vide MM office memo no. Ch-75/DH-1596 dated 29.03.2019.

Your firm vide its letter no. HWIPL/REJECTION-2018-19 dated 30.03.19, received on 26.04.19 submitted reply to ibid notice. The contents of your reply were considered and not found tenable.

Further, the firm vide its letter no HWIPL/DH-1596 /RC-105/2019-20 dated 09.05.19 was requested that the rejected entire material of two lots i.e. 52 MT, GI wire 7/8 SWG may be returned to the firm and the amount of penalty & LD charges may be recovered from the pending payments.

The SPC in its meeting held on 05.07.19 observed that M/s Himachal Wire Industries Pvt Ltd., Distt. Kangra violated the terms of NIT/RC/PO and repeatedly supplied sub-standard or defective material, not confirming to the prescribed specification against this PO and supplies against PO DH-1636 as well and after due deliberations decided as under:-

1. The request of the firm regarding lifting of rejected entire material of two lots i.e. 52 MT, GI wire 7/8 SWG may be accepted as the amount of penalty & LD charges against this PO has been recovered by O/O FA&CAO/MM, DHBVN, Hisar.
2. To recommend the case to WTDs for deliberation and further recommendation to BODs that M/s Himachal Wire Industries Pvt Ltd., Distt. Kangra may be Blacklisted for a period of 3 year on account of supply of sub-standard/defective material not conforming to the prescribed specification of Nigam which persistently failed in NABL testing

B- Purchase order no. DH-1636/RC-105/QH-II/1930/XEN/MM-II dated 05.02.18

Purchase Order no. DH-1636/RC-105/QH-II/1930/XEN/MM-II dated 05.02.18 placed upon your firm for supply of 104 MT, GI wire 8 SWG (4mm). Accordingly, after getting pre dispatch inspections of the material by DHBVN officers, DI (4 Lots) were issued by MM office for supply of material to designated Nigam's Stores. The status of material supplied by the firm and sample testing thereof from NABL lab is elaborated as under:-

Sr. No.	Description of Material	DI no. & Date	Qty. in MT	Sample testing status & issue- ability
1	G.I Wire 8 SWG (4 mm)	Ch-07/DH-1636 dated 20.04.18	26	Sample results did not found in order.
2		Ch-15/DH-1636 dated 17.05.18	26	Sample results did not found in order.
3		Ch-20/DH-1636 dated 30.05.18	26	Lot made issuable without sending sample.
4		Ch-33/DH-1636 dated 12.07.18	26	Sample results did not found in order.
			104	

From the above, it is evident that out of the 104 MT G.I Wire 8 SWG (4 mm) supplied by your firm, the material of 3 lots (78 MT) failed in testing from NABL lab M/s Shri Ram Institute for Industrial Research, New Delhi. As per test reports, samples selected and sealed from DI no. **Ch-07/DH-1636 dated 20.04.18, Ch-15/DH-1636 dated 17.05.18 & Ch-33/DH-1636 dated 12.07.18** did not conform to IS: 280: 2006 as Mass of Zinc Coating on G.I. Wire was not found within permissible limit.

Your firm vide MM office memo nos. Ch-26/DH-1636/RC-105 dated 27.06.18, Ch-42/DH-1636/RC-105 dated 16.08.18 & Ch-52/DH-1636/RC-105 dated 27.11.18 was requested to replace the aforementioned material. But your firm did not respond. This shows that your firm did not take keen interest to replace the said material of 3 lots rejected by Nigam.

The detailed case as brought out above was considered by SPC in its meeting held on **04.01.2019**. SPC observed that the GI wire 8 SWG (4mm) supplied by the firm has repeatedly failed in quality tests which shows that the firm is not adhering to quality of material as per Nigam's Technical Specifications and has supplied the sub-standard material. Accordingly, after due deliberation, SPC decided to recommend to WTDs as per details noted below:-

1. To reject the entire material of 78 MT G.I Wire received against DI no. Ch-07 dated 20.04.18 (26 MT), Ch-15 dated 17.05.18 (26 MT) & Ch-33 dated 12.07.18 (26 MT) of MM office P.O. No. DH-1636/RC-105/QH-II/1930/XEN/MM-II dated 05.02.18 supplied by M/s Himachal Wire Industries Pvt Ltd., Distt. Kangra on account of failure of sample. The firm shall be asked to lift back the rejected material after recovery of all the penalties/LD charges etc.
2. To recover the cost of sample testing from the firm alongwith expenditure incurred by Nigam for conducting pre-dispatch inspection of the aforementioned material (qty. against 3 no. D.Is). In addition to this, a penalty @5% of cost of the rejected lots of material shall also be recovered from firm by FA & CAO/MM, DHBVN, Hisar.
3. The Purchase Order no. DH-1636RC-105/QH-II/1930/XEN/MM-II dated 05.02.2018 may be terminated and Liquated damages (L.D.) charges @ 5% of cost of the material rejected in NABL testing and lying in stores i.e. 78 MT, GI Wire received against PO No. DH-1636/RC-105/QH-II/1930/XEN/MM-II dated 05.02.18 may be imposed upon the firm.
4. In case of non-deposit of amount of penalties and LD charges etc. as per sr. no. 2 and 3 above, the Nigam may set off the claim from the due payments (including security deposits returnable to the supplier) of firm or firm's B.G. may be encashed to set off the pending liabilities of the Nigam & balance payment, if left-out (after clearance of all liabilities of Nigam) may be refunded to the firm.
5. Action against the firm for blacklisting for a period of next three years on account of supply of sub-standard material, may be initiated by serving notices of 15 and 21 days to the firm.

As per recommendation of SPC, the case was considered by the WTDs of DHBVN in its meeting held on 09.02.19 against agenda item no. 178.16 and it was decided to approve the above proposals mentioned from point no. 1 to 5.

Accordingly , a notice of 15 days was served upon your firm vide MM office memo no Ch-60/DH-1636 dated 25.02.19 to explain the position as to why the firm should not be blacklisted on account of supplying the below standard material to Nigam and thus indulging in breach of contract in completing the supplies against subject cited P.O.

Your firm vide its letter no. HWIPL/REJECTION-2018-19 dated 06.03.19 submitted its reply to ibid notice. The same were considered by MM wing & not found tenable.

Further, Your firm vide its letter no HWIPL/DH-1636 /RC-105/2019-20 dated 09.05.19 has requested that the rejected entire material of three lots i.e. 78 MT, GI wire 7/8 SWG may be returned to the firm and the amount of penalty & LD charges may be recovered from the pending payments.

The SPC in its meeting held on 05.07.19 and observed that your firm had violated the terms of NIT/RC/PO and repeatedly supplied sub-standard defective material, not conforming to the prescribed specification against this PO and supplies against PO DH-1596 as well and after due deliberations decided as under:-


1. The request of the firm regarding lifting of rejected entire material of three lots i.e. 78 MT, GI wire 7/8 SWG has been considered and accepted, as the amount of penalty & LD charges against this PO stands already recovered by O/O FA&CAO/MM, DHBVN, Hisar.
2. To recommend the case to WTDs for deliberation and further recommendation to BODs that M/s Himachal Wire Industries Pvt. Ltd., Distt. Kangra may be blacklisted for a period of 3 year on account of supply of sub-standard/defective material not conforming to the prescribed specification of Nigam which persistently failed in NABL testing.

As per proposals/recommendations of SPC, an agenda (vide Agenda Item No. 194.06) was considered by the Whole Time Directors at their meeting held on 26th July, 2019. It was resolved as under:-

"The WTDs considered the proposal contained in the memorandum and approved the same".

In pursuance to ibid recommendation of WTDs, an agenda was put up before BODs of DHBVN in its meeting held on 20.09.2019 for seeking approval on blacklisting of your firm on account of above default. The Board of Directors considered the memorandum and approved the proposal.

Accordingly, your firm M/s Himachal Wire Industries Pvt. Ltd., Distt., Kangra having Registered office and Works at Industrial Avenue, G.T. Road, Dhamtal-176403 (Near Pathankot) Distt-Kangra, Himachal Pradesh is hereby blacklisted for a period of 3 years (from the date of issuance of communication).


Chief Engineer/MM
DHBVN Hisar

CC to

1. SPS to Chairman-cum-Managing Director, DHBVN/UHBVN, Hisar/Panchkula for kind information of the Chairman-cum-Managing Director, please.
2. SPS to Director/Projects, DHBVN, Hisar for kind information of Director/Projects, please.
3. SPS to Director/Projects, Director/Operation, UHBVN, Panchkula for kind information of Director/Projects, Director/Operation, UHBVN, Panchkula.
4. The Managing Director, Haryana Vidyut Prasaran Nigam Ltd., Shakti Bhawan, Sector-6, Panchkula-134109.
5. The Managing Director, Haryana Power Generation Corporation Ltd., Shakti Bhawan, Sector-6, Panchkula-134109.
6. The Chairman & Managing Director of Punjab State Power Corporation Limited, the Mall, Patiala-147001.
7. The Chairman & Managing Director of Punjab State Transmission Corporation Limited, the Mall, Patiala-147001.
8. The Secretary, Himanchal Pradesh State Electricity Board, Vidyut Bhawan, Shimla-171002.
9. The Managing Director, Uttranchal Pwer Corporation Limited, Dehradun (Uttranchal).
10. The Chairman, Tata Power Delhi Distribution Limited, Tata Power DDL House, Hudson Lines, Kingsway Camp., New Delhi-110009.
11. The Chairman-cum-Managing Director, Delhi Transco Ltd., Shakti Sadan, Kotla Road, New Delhi-110002.
12. The Managing Director, Jodhpur Vidyut Vitran Nigam Ltd., New Power House, Industrial Area, Jodhpur (Rajasthan).
13. The Chairman & Managing Director, Jaipur Vidyut Vitran Nigam Ltd., Vidyut Bhawan, Janpath, Jaipur-302005 (Rajasthan).
14. The Chairman, U.P. Power Corporation Limited, Shakti Bhawan, 14, Ashok Marg, Lucknow-226001.
15. The Chairman & Managing Director, Rajasthan Rajya Vidyut Prasaran Nigam Limited, Vidyut Bhawan, Janpath, Jaipur (Rajasthan)-302005.
16. The Secretary Rajasthan Rajya Haryana Vidyut Prasaran Nigam Ltd., Vidyut Bhawan, Jyoti Nagar, RC Dave Marg, Jaipur - 302005.
17. The Chairman, Ajmer Vidyut Vitran Nigam Limited, Hathi Bhata, Jaipur Road Ajmer.
18. The Chairman & Managing Director, Rajasthan Rajya Vidyut Utpadan Nigam Limited, Vidyut Bhawan, Janpath, Jaipur (Rajasthan) - 302005.

19. The Chairman, Madhya Pradesh State Electricity Board, PO Box No. 34 Rampur, Jabalpur-432008.
20. The Chairman, West Bengal State Electricity Board, Bidhan Nagar, Kolkata.
21. The Chairman, J & K State Electricity Board, Jammu.
22. Managing Director, West Bengal State Electricity Distribution Company Ltd., Block DJ, 5th Floor, Vidyut Bhawan, Salt, Lake City Sector-2, Kolkata-700091.
23. Managing Director, Mangalore Electricity Supply Co. Ltd., (MESCOM), Paradigm Plaza, AB Shetty Circle, Pandeshwara, Manglore-575001.
24. Managing Director, Hubli Electricity Supply Co. Ltd., (HESCOM), Nava Nagar Post, Corporate Office, Hubli-580025 (Karnataka).
25. Managing Director, Gulbaraga Electricity Supply Co. Ltd., (GESCOM), Gulbarga Main Road, Kulbaraga-585102 (Karnataka).
26. Managing Director, Chamundeshwari Electricity Supply Co. Ltd., (GESCOM), No. 927, LJ Avenue Commercial Complex, New Kantaraj Urs Road, Sarawatipuram, Musore-570009, Karnataka.
27. Managing Director, Hukeri Rural Electric Co-Operative Society Ltd., Hukeri Dist., Belagaum, Karnataka.
28. Chairman and Managing Director, Southern Power Distribution Company of Telangana Ltd., Corporate Office 3, 6-1-50, Mint Compound, Hyderabad-560063.
29. Chairman and Managing Director, APEPDCL, Corporate Office, P & T Colony, Seethammadhara, Vishakapatnam-530013 (AP).
30. Chairman and Managing Director, Northern Power Distribution Co, of AP Ltd., H. No-1 1-503, Op: NIT Petrol Pump, Chaitanyapuri Colony, Hanamkonda, Warrangal-506004 (A.P.).
31. Chairman and Managing Director, Southern Power Distribution Co, of AP Ltd., behind sreenivasa Kalyanamantapam, Tirichannur Road, Tiripathi-517101, Chittoor District, AP.
32. Managing Director, Anakapally Rural Electric Co-Operative Society Ltd., No B-1539, Kasimkota, Dist., Visakapatnam, AP.
33. Managing Director, Cheepurapalli Rual Electric Co-Operative Society Ltd., No. VR-300 Cheepurapalli, Dist. Vizianagaram, AP.
34. Managing Director, Co-Operative Electric Supply Society Ltd., Kuppam Dist., Chottor, AP.
35. Managing Director, Co-Operative Electric Supply Society Ltd., Sircilla Dist., Karimnagar, AP.
36. Chairman Assam Power Distribution Company Ltd., 4th Floor, Bijulee Bhawan, Paltan Bazar, Guwahati-781001, Assam-India.
37. The Secretary, Bihar State Electricity Board, Vidyut Bhawan, Balley Road, Patna 800021.
38. Managing Director, North Bihar Power Distribution Co. Ltd., Vidyut Bhawan, Railway Road, Patna-800021 (Bihar).
39. Chairman, Chattisgarh State Power Distribution Company Ltd., Danganiya, PO Sunder Nagar, Raipur-492013.
40. Managing Director, Dakshin Gujrath Vij Co. Ltd., Nana Varcha Road, Near Kopadara Char Rasta, Surat-395006 (Gujrath).
41. Managing Director, Paschim Gujrath Vij Co. Ltd., Nana Mava Main Road, Laxmi Nagar, Rajkot.
42. Managing Director, Madhaya Gujrath Vij Co. Ltd., Sardar Patel Vidyut Bhawan, Racecourse Road, Vadodara-390007 (Gujrath).
43. Chairman, Uttar Gujrath Vij Co. Ltd., Visragar Road, Mehsana-284001.
44. Director (Tech.) Jharkhand Bijlee Vitaran Nigam Ltd., Engineering Bldg. HEC, PO Dhurwa, Ranchi Jharkand-834004.
45. The Chairman & Managing Director, (EZ) N.O. Porva Kshethra Vidyut Vitaran Company Ltd., Shakti Bhawan, Vidyut Bhawan, Jabalpur (M.P.).
46. The Chairman & Managing Director, (CZ) Madhaya Kshethra Vidyut Vitaran Company Ltd., Govindpura, MPSEB Complex, Bhopal-462023 (M.P.).
47. Chairman & Managing Director, MP Paschim Kshethra Vidyut Vitaran Company Ltd., GPH Compound, Pologround, Indore (MP).
48. Managing Director Maharashtra State Electricity Distribution Co. Ltd., 6F, Prakshgadh, Plot No-G-9, Bandra E, Mumbai-400051, Maharashtra.
49. Managing Director, Ajmer Vidyut Vitaran Nigam Ltd., Old Power House, Jaipur Raod, Ajmer (Rajasthan).

50. Chairman & Managing Director, Tamilnadu Generation & Distribution Corporation 800, Electricity Avenue, Anna Salai, Chennai-600002 (Tamil Nadu).
51. Managing Director, Purvanchal Vidyut Vitaran Nigam Ltd., Vidyut Nagar, PO DLW, Hydell Colony, Bhikaripur, Varanasi-221004 (UP).
52. Managing Director, Mazdhyanchal Vidyut Vitaran Nigam Ltd., 4-A, Gokhle Marg, Lucknow-226001 (UP).
53. Managing Director, Pashehimachal Vidyut Nigam Ltd., Victoria Park, Meerut-256001.
54. Managing Director, DVVNL, 220 KV Gss, Agra Mathura Bye Pass, Sikandra, Agra-282007.
55. Chairman, West Bengal State Electricity Distribution Co. Ltd., Vidyut Bhawan, DJ Block Sector-2, Salt Lake City, Bidhan Nagar, Kolkata-700091.
56. The Secretary Orissa State Electricity Board, Bhubaneswar.
57. The Chairman-cum-Managing Director, Andhra Pradesh Power Generation Corporation Ltd., Vidyut Soudha, Hyderabad-5000802.
58. The Managing Director, Chhattisgarh State Power Holding Co. Ltd., Vidyut Sewa Bhawan, Dangania, Raipur.
59. The Managing Director, Chhattisgarh State Power Distribution Co. Ltd., Vidyut Sewa Bhawan, Dangania, Raipur.
60. The Managing Director, Chhattisgarh State Power Generation Co. Ltd., Vidyut Sewa Bhawan, Dangania, Raipur.
61. The Managing Director, Chhattisgarh State Power Transmission Co. Ltd., Vidyut Sewa Bhawan, Dangania, Raipur.
62. The Managing Director, Chhattisgarh State Power Trading Co. Ltd., Vidyut Sewa Bhawan, Dangania, Raipur.
63. The Executive Director (S&P), C.S.P.D.C.L., Raipur.
64. The Secretary, Bihar State Electricity Board, Vidyut Bhawan, Bailey Road, Patna-800021.
65. The Secretary, Gujrat Ujra Vikas Nigam, Sardar Patel Vidyut Bhawan, Race Course, Vadodara-390007.
66. The Secretary, Haryana Vidyut Prasaran Nigam Ltd., / M.D. Haryana Power Generation Corporation Ltd., Shakti Bhawan, Sector-6, Panchkula (Haryana)-134109.
67. The Secretary, Karnatka Power Transmission Corporation Ltd., Corporate Office, Kala Bhawan, Banglore-56009.
68. The Secretary, Meghalya State Electricity Board, Lum Jinsgshal, Round Road, Shillong-793001.
69. The Secretary, Kerla State Electricity Board, Vaidhyuthi Bhawan, Pattorn, Thiruvanantha Puram-695001.
70. The Secretary, Grid Corporation of Orissa Ltd., Janpath, Bhubneshwar (Orissa) - 751022.
71. The Secretary, Rajasthan Rajya Vidyut Prasaran Nigan Ltd., Vidyut Bhawan, Jyoti Nagar, R.C. Dave Marg, Jaipur-302005.
72. The Secretary, Tamil Nadu Electricity Board, 9th Floor, N.P. K. P. R. Malligal, 800, Anna Salai, Chennai-600002.
73. The Chairman-cum-Managing Director, Uttar Pradesh Power Corporation, Shakti Bhawan, 14- Ashok Marg, Lucknow (UP)-226001.
74. The Secretary, West Bengal State Electricity Board, Vidyut Bhawan, 7th Floor, Bidhdannagar, Kolkata (WB)-700091.
75. The Chief Engineer (MM) Central Purchase Organisation, Punjab State Electricity Board, the Mall, Patiala-147001.
76. The Chief Engineer (MM) Vidyut Sadan, Dakshin Haryana Bijli Vitran Nigam Ltd., Hisar-125005.
77. Ahmadabad Electricity Company Ltd., Ahmadabad-380001.
78. The Chief Engineer Transmission, Vidyut Soudha, Transmission Corporation of Andhra Pradesh Ltd., Hyderabad-500082.
79. The Chief Engineer (S&P), Engg. Building H.E.C. Dhurwa, Jharkhand State Electricity Board, Ranchi-834004.
80. The Chief Engineer (A&F), BSES Bhawan, Nehru Place, BSES Rajdhani Power Ltd., New Delhi-110019.
81. North Delhi Power Ltd., Grid Sub Station Building, Hudson Lines, Kings Way Camp Delhi-110009.

82. The General Manager, P&MM, APNPDDI, H. no- 1-1-478 & 503, Opp. REC Petrol Pump, Chaitanyanpuri, Hanamkonda Warrangal-506004.
83. The Chief General Manager. P&MM & Operation. APCPDDI, H. No-11-04-660, 3rd Floor, Singarani Bhawan, Adjacent to Hanuman Temple, Khairatabad, Hyderabad-500004.
84. The Chief Engineer Manager, Operation & Material, APEPDCL, H. No-30- 14-9, Near Saraswathi Park, Daba Gardens, Visakhapatnam-530020.
85. The Superintending Engineer, MIAO Electrical Circle, Department of Power, MIAO, Arunachal Pradesh.
86. All CEs in UHBVN/DHBVN/HVPN/HPGCL.
87. LR, HPU, Shakti Bhawan, Panchkula for information please.
88. All SEs (OP)/SE/Const., in UHBVN/DHBVN.
89. SE/IT DHBVN, **Hisar for uploading the order on Nigam's website.**
90. FA&CAO/MM in UHBVN/DHBVN/HVPN/HPGCL.
91. SE/S&W, UHBVN, Dhulkote.
92. Chief Auditor, UHBVN/DHBVN.
93. COS, DHBVN, Hisar.
94. All XENs Central Store, UHBVN/DHBVN.
95. Company Secretary, UHBVN/DHBVN/HVPN/HPGCL.
96. Supdt. /Purchase, DHBVN, UHBVN, Hisar/Panchkula.